
Gel Cell
12V (2)
Battery
+12V
Press Vlv
Indicator
Fuel
ShutOff
18 VDC
620 MA
< 10 Sec
FMV T/M
ll VDC
220 MA
Battery Check
SOV Solenoid
Drive Circuit
SOV Solenoid
Drive Circuit
FMV Torque
Motor Circuit
Volt
Meter
Volt
Meter
Current
Meter
Current
Meter
Hand Select the 1-Ohm dropping resitor to be in the high side so this
calibration technique can work.
Set VR29 so that
integrator (CT A2C) for FMV
current level drifts to
zero mA.